



Tractors

Date: 14/06/2024 Location: 524 Quinalow-Peranga Rd, Peranga

Machine Type: Tractor FWA

Make: John Deere	<u>Model</u> : 6830	<u>Hours</u> : 15,211	
Serial Number: LO683	0P618534	<u>Auto Steer</u> : No	
<u>Clean</u> : <mark>Yes</mark> /No		Transmission: IVT	
Engine Oil Analysis:	Yes/ <mark>No</mark>	Hydraulic Oil Analysis:	Yes/ <mark>No</mark>
Coolant Analysis:	Yes/ <mark>No</mark>	Diff/Planetary/Main Gearbox:	Yes/ <mark>No</mark>
Operated:	Yes/ <mark>No</mark>	Started/Ran:	<mark>Yes</mark> /No
Visual Inspection			

Item	ОК	Not Ok	Comments
Engine Oil	1 1		
	\checkmark		
Engine			Infrared Thermal Test: Good
Temperature	V (
Last Service	\checkmark		14,840hrs
Leaks		X	Slight fuel leak around filter hoses
Filters			
Air Cleaner	~		Near new element
Turbo/Exhaust	>		
Wiring/Alternator	~		
Belts/Hoses/Clamps	~		
Radiator	~	4	
Oil Coolers	~		
Screen	\checkmark		
Fuel Pump	~		
Fuel Injectors	>		
Fuel Tank	 Image: A second s	λ	
Batteries	× (
Corrosion	 ✓ 	()	6
Covers/Guards	\checkmark		PTO Guard missing
Front Planetary Seals	\checkmark		
Rear Axle Seals	 ✓ 		Slight weep on axle seals
Front Diff	\checkmark		
Rear Diff	\checkmark		
Drive Shafts	\checkmark		
Suspension	~		
Recent Repairs			





Transmission & Hydraulics

Oil Level	\checkmark	
Transmission	\checkmark	
Powershift		N/A
IVT/CVT	\checkmark	
Hyd Pumps	\checkmark	
Hyd Cylinders	\checkmark	
Valve Blocks		
Steering	 ✓ 	
Remote Couplings	\sim	
Leaks		Small leaks. None major
Three Point Linkage		

Cab, Electrical and Tyres

Cab	(
Air Conditioner	\checkmark		
Radio	\checkmark		
Two-way Radio	1		Not fitted
Windows	~		
Upholstery	x		Roof lining falling down. Seat material torn
Seat Condition/Function	x		Function good. Material torn
Switches	✓		
Function Controls	✓		
Lights	x		Front lights broken
Screens	~		
Monitors			No monitors fitted
Mounting Points			
Overall Condition And Comments	6	J	Cab in OK condition considering age. Lights in bonnet broken
Tyres		1	
Tyre Size			Front 480/65/R28 Rear 600/65/38
Duals			No
Wheel Condition	\checkmark		
Tyre Condition	~		Front tyres are good. Rear, as new
Tread Depth			Front: 31mm Rear: 50mm
Tracks			
Track Condition			N/A
Tread Depth			
Drive Lugs			
Alignment			





Idler Condition		
Tensioner		
Condition		
Overall Comments		For a tractor that has done 15,000 + hours it is in reasonably good condition, with a few minor leaks. Bonnet lights are broken. Hydraulic top link is handy.
		-

