

## **LOT 26**

<u>Date:</u> 11/02/2025 Location: Reardon Farms, Bungunya

Machine Type: Chisel Plough

Make: Gessner Model: HR1200

Serial Number: 070

<u>Clean</u>: Yes/No <u>Covers off</u>: Yes/No

Operated: Yes/No

## Visual Inspection

Item	ОК	Not	Comments
iteili	UN UNITED STATES	OK	Confinents
Pull & Frame		1	Some crack repairs
	<b>V</b>		
Tynes	<b>~</b>		Middle tyne bent.
Points			Chisel Points
Tyne Rams	<b>✓</b>		Many to most tyne ram seals leaking
Tyne Pins	✓		Looks to be greased. Assume some do not take grease
Hyd Hoses	V		Most tyne hoses ok. Lift/Fold hoses frayed
Hyd Rams	<b>V</b>		Lift Ram Seal Leak
Wheels & Tyres	<b>✓</b>	19	One Lift tyre worn on sidewall
Spacing			300mm
Width			12m
Overall	\		OK Condition. Most tyne ram seals need replacing. One
	-		lift ram seal. Some crack repairs to watch
	Ŋ.		
	1	9	