

Grain Harvesting Equipment

<u>Date:</u> 11/07/2025	Location: Tichborne NSW	Machine Type: Header
Make: New Holland	<u>Model</u> : CR9.90	Hours: Eng: 478hrs Sep: 354hrs
<u>Clean</u> : <mark>Yes</mark> /No	Serial Number: HAFR992HLN20	071003
Engine Oil Analysis:	Yes/ <mark>No</mark>	<u>Hydraulic Oil Analysis</u> : Yes/ <mark>No</mark>
Coolant Analysis:	Yes/ <mark>No</mark>	<u>Diff/Planetary/Main Gearbox</u> : Yes/ <mark>No</mark>

Includes MacDon 140 Front and Trailer

Engine: Visual Inspection

Item	ОК	Not Ok	Comments
Engine Oil	√		
Engine Temp			Infrared Thermal Test
Last Service			
Leaks	V (
Filters	\checkmark		
Air Cleaner			
Turbo/Exhaust	~		
Wiring/Alternator	~		Test - Multimeter
Belts/Hoses/Clamps	~		
Radiator	~		
Oil Coolers	\checkmark		
Screens	\checkmark		
Fuel Pump	✓ \		
Fuel Injectors	✓ \		
Fuel Tank	 Image: A second s		
Batteries			
Corrosion	✓ ((.]	
Covers/Guards	\checkmark		
Overall Appearance	\checkmark		

Hydraulic/Mechanical Drive System

Oil Level	\checkmark	
Hyd engage Drive	\checkmark	Main Rotor. Cutter Bar/Front Drive/ Unload Auger
Units		
Hyd Pumps	\checkmark	
Hyd Cylinders	\checkmark	
Valve Blocks	\checkmark	



Steering	\checkmark	
Hydrostatic Drive	~	
Quick Couplings	\checkmark	
Leaks	\checkmark	

Separator/Cleaning System

Rotor Type: Twin Rotor

Feeder House	\checkmark		
Feeder House Chain	\checkmark		
Drive Belts/Chains			
Rotor Condition	~		
Rotor Bearing/s	\checkmark		
Threshing Elements	1		
Rotor Belt			
Rotor Drive Clutch			
Rotor Drive Gearbox	\checkmark		
Top Cover	~		
Concaves	V (
Discharge Beater	\checkmark		
Straw Walkers			
Sieves			
Sieve Arms/Bushes	✓		
Fan	~		
Clean Grain Elevator	\checkmark		
Cross Auger	\checkmark		
Returns	\checkmark		
Grain Tank			
Unload Auger	✓		Length
Sample System	√		
Moisture Meter	16		
Grain Loss Monitors	✓		6.
Scales/Yield Monitors	✓		
Adjustments	1	1	
Rotor Speed	✓		
Concave Clearance	· ·		
Fan Speed	· ✓		
Sieve Settings	· ·		
Others			
Choppers and Spreaders			
Drive Belt/Pullies	\checkmark		
Chopper Knives			



Spreaders	\checkmark	
Spreader Drive	\checkmark	
Grease Points/		
Auto Greaser		

Cab			
Air Conditioner			
Radio	\checkmark		
Two Way Radio 🛛 🔍	\checkmark		
Screens/Monitors	1		
Auto Steer			
Upholstery	~		
Seat Condition/Functions	10		
Functions/Main Contro	ls		Clearing Sale Conditions. Could not operate or put front on.
Front Up/Down			
Reel Up/Down			
Reel In/Out			
Front Tilt			
Reel Speed			
Auto Steer			
Auger In/Out			
Auger Start/Stop			
Drive Fwd/Back			
Pre Set Height			
Separator Start			
Front Start			
Adjustment Controls			
Rotor Speed		()	
Concave Clearance			
Sieve Settings)
Fan Speed			
Engine Revs			
Park Brake			
Grain Loss Monitors			
Lights			
Grain Tank Window			
Orange Beacons			
Mirrors			
Overall Condition			Header and Front are in excellent condition. Serviced and clean.



