



Lot 1

<u>Date:</u> 05/08/2025 <u>Location</u>: Ouyen, Victoria <u>Machine Type</u>: FWA Tractor

Make: Case IH Model: 2022 Optum 300 Hours: 1470

<u>Serial Number</u>: **DBDP300CNDP54611** <u>Auto Steer</u>: **RTX + Integrated Receiver**

<u>Clean</u>: Yes/No <u>Transmission</u>: CVT

Engine Oil Analysis: Yes/No Hydraulic Oil Analysis: Yes/No

<u>Coolant Analysis</u>: Yes/No <u>Diff/Planetary/Main Gearbox</u>: Yes/No

Visual Inspection

| visual ilispection | | | |
|-----------------------|------------|--------|-------------|
| Item | ОК | Not Ok | Comments |
| Engine Oil | 1 | | |
| Engine | 1 | | |
| Temperature | / Y | | |
| Last Service | / / | | Service Due |
| Leaks | ~ | | |
| Filters | V | | |
| Air Cleaner | V | | |
| Turbo/Exhaust | ~ | | |
| Wiring/Alternator | | | |
| Belts/Hoses/Clamps | V | | |
| Radiator | ~ | | |
| Oil Coolers | ~ | | |
| Screen | V | | |
| Fuel Pump | ~ | | |
| Fuel Injectors | ~ | | |
| Fuel Tank | ~ | | |
| Batteries | ✓ | | |
| Corrosion | ~ | | |
| Covers/Guards | ~ | | |
| Front Planetary Seals | ~ | | |
| Rear Axle Seals | V | | |
| Front Diff | ~ | | |
| Rear Diff | ~ | | |
| Drive Shafts | ~ | | |
| Suspension | ~ | | |
| | | | |
| Recent Repairs | | | |





Transmission & Hydraulics

| Oil Level | ~ | |
|---------------------|----------|----------|
| Transmission | ~ | |
| Powershift | | |
| IVT/CVT | ~ | |
| Hyd Pumps | ~ | |
| Hyd Cylinders | ~ | |
| Valve Blocks | ~ | |
| Steering | ~ | |
| Remote Couplings | ~ | |
| Leaks | Y | No Leaks |
| Three Point Linkage | / | |

Cab, Electrical and Tyres

| Cab | | |
|-----------------------------------|------------|------------------------------------|
| Air Conditioner | ✓ (| |
| Radio | V | |
| Two-way Radio | | |
| Windows | V | |
| Upholstery | V | |
| Seat Condition/Function | | |
| Switches | ✓ | |
| Function Controls | * | |
| Lights | ✓ | |
| Screens | ✓ | |
| Monitors | ✓ | |
| Mounting Points | V | |
| Overall Condition And Comments | | Excellent |
| Tyres | | |
| Tyre Size | F | Rear: 710/70/R42 Front: 600/70/R30 |
| Duals | | |
| Wheel Condition | ✓ | |
| Tyre Condition | ✓ | |
| Tread Depth | F | Rear: 52mm Front: 45mm |
| Tracks | | |
| Track Condition | | |
| Tread Depth | | |
| Drive Lugs | | |
| Alignment | | |
| Idler Condition | | |
| Tensioner | | |
| Condition | | |





| Overall Comments | Excellent Condition. |
|------------------|----------------------|
| | |
| | |
| | |
| | |
| | |
| | |

