

## Date:23/07/2025Location: Moama, NSWMachine Type:Chaser BinMake:DunstanModel:Serial Number:212329Clean:Yes/NoCovers off:Operated:Yes/No

## Visual Inspection

Item	ОК	Not OK	Comments
Pull & Frame	~		
PTO & Clutch	-		
Gearbox	~		
Drive Chains	~	(	
Hyd Hoses	>		
Hyd Fittings	~		
Hyd Rams	×	)	
Bottom Auger	<	1	
Unload Auger	~		
Wheels	~		
Tyres	~		
Steering			N/A

Chaser Bin is in excellent condition.

Roll over tarp looks good

Cover at bottom of unload auger was not off to have a look inside.

Contact Vendor for Unload Auger Size.