



Tractors

<u>Date:</u> 23/07/2025 <u>Location</u>: Moama, NSW <u>Machine Type</u>: FWA Tractor

Make: John Deere Model: 8295R Hours: 2778

<u>Serial Number</u>: 1RW8295RLLS152293 <u>Auto Steer</u>: Starfire 6000 + 4600 Screen

<u>Clean</u>: Yes/No <u>Transmission:</u> Powershift

Engine Oil Analysis: Yes/No Hydraulic Oil Analysis: Yes/No

<u>Coolant Analysis</u>: Yes/No <u>Diff/Planetary/Main Gearbox</u>: Yes/No

Visual Inspection

Item	ОК	Not Ok	Comments
Engine Oil	4		
Engine	/ /		Clearing Sale Conditions. Tractor was started but not run and
Temperature			driven.
Last Service	V		2750 Hrs
Leaks	V		
Filters	~		
Air Cleaner	V		
Turbo/Exhaust	V		
Wiring/Alternator	✓		
Belts/Hoses/Clamps	~		
Radiator	~		
Oil Coolers	~		
Screen	~		
Fuel Pump	~		
Fuel Injectors	✓		
Fuel Tank	~		
Batteries	~		
Corrosion	V		
Covers/Guards	>		
Front Planetary Seals	~		
Rear Axle Seals	~		
Front Diff	~		
Rear Diff	~		
Drive Shafts	~		
Suspension	~		
Recent Repairs			





Transmission & Hydraulics

Oil Level	~	
Transmission	~	
Powershift	~	
IVT/CVT		N/A
Hyd Pumps	>	
Hyd Cylinders	~	
Valve Blocks	~	
Steering		
Remote Couplings	/	
Leaks	/	No Leaks Found
Three Point Linkage	<	

Cab, Electrical and Tyres

Cab		
Air Conditioner	V	
Radio	V ()	
Two-way Radio	✓	
Windows	V	
Upholstery	✓	
Seat Condition/Function	_	
Switches	✓	
Function Controls	V	
Lights	✓	
Screens	✓	
Monitors	✓	
Mounting Points	✓	
Overall Condition And Comments		Excellent Condition
Tyres		6
Tyre Size		Front: 480/70/R34 Rear: 520/85/R46
Duals		Rear Duals
Wheel Condition		
Tyre Condition		
Tread Depth		Rear: Inner and Outer 45mm Front: 37mm
		1850mm wheel centers
Tracks		
Track Condition		
Tread Depth		
Drive Lugs		
Alignment		
Idler Condition		





Overall Comments	Tractor is in excellent condition. Could not find a fault. No Fault Codes. Very well looked after.
Overall Comments	
Overall Comments	
	No Fault Codes. Very well looked after.

