



Tractors

Date: 23/07/2025

Location: Moama, NSW

Machine Type: FWA Tractor

Make: John Deere

Model: 8295R

Hours: 2778

Serial Number: 1RW8295RLLS152293

Auto Steer: Starfire 6000 + 4600 Screen

Clean: Yes/No

Transmission: Powershift

Engine Oil Analysis: Yes/No

Hydraulic Oil Analysis: Yes/No

Coolant Analysis: Yes/No

Diff/Planetary/Main Gearbox: Yes/No

Visual Inspection

| Item | OK | Not Ok | Comments |
|-----------------------|----|--------|---|
| Engine Oil | ✓ | | |
| Engine Temperature | ✓ | | Clearing Sale Conditions. Tractor was started but not run and driven. |
| Last Service | ✓ | | 2750 Hrs |
| Leaks | ✓ | | |
| Filters | ✓ | | |
| Air Cleaner | ✓ | | |
| Turbo/Exhaust | ✓ | | |
| Wiring/Alternator | ✓ | | |
| Belts/Hoses/Clamps | ✓ | | |
| Radiator | ✓ | | |
| Oil Coolers | ✓ | | |
| Screen | ✓ | | |
| Fuel Pump | ✓ | | |
| Fuel Injectors | ✓ | | |
| Fuel Tank | ✓ | | |
| Batteries | ✓ | | |
| Corrosion | ✓ | | |
| Covers/Guards | ✓ | | |
| Front Planetary Seals | ✓ | | |
| Rear Axle Seals | ✓ | | |
| Front Diff | ✓ | | |
| Rear Diff | ✓ | | |
| Drive Shafts | ✓ | | |
| Suspension | ✓ | | |
| | | | |
| Recent Repairs | | | |



Transmission & Hydraulics

| | | | |
|---------------------|---|--|----------------|
| Oil Level | ✓ | | |
| Transmission | ✓ | | |
| Powershift | ✓ | | |
| IVT/CVT | | | N/A |
| Hyd Pumps | ✓ | | |
| Hyd Cylinders | ✓ | | |
| Valve Blocks | ✓ | | |
| Steering | ✓ | | |
| Remote Couplings | ✓ | | |
| Leaks | ✓ | | No Leaks Found |
| Three Point Linkage | ✓ | | |

Cab, Electrical and Tyres

| | | | |
|-----------------------------------|---|--|--|
| Cab | | | |
| Air Conditioner | ✓ | | |
| Radio | ✓ | | |
| Two-way Radio | ✓ | | |
| Windows | ✓ | | |
| Upholstery | ✓ | | |
| Seat Condition/Function | ✓ | | |
| Switches | ✓ | | |
| Function Controls | ✓ | | |
| Lights | ✓ | | |
| Screens | ✓ | | |
| Monitors | ✓ | | |
| Mounting Points | ✓ | | |
| Overall Condition And Comments | | | Excellent Condition |
| Tyres | | | |
| Tyre Size | | | Front: 480/70/R34 Rear: 520/85/R46 |
| Duals | | | Rear Duals |
| Wheel Condition | | | |
| Tyre Condition | | | |
| Tread Depth | | | Rear: Inner and Outer 45mm Front: 37mm |
| | | | 1850mm wheel centers |
| Tracks | | | |
| Track Condition | | | |
| Tread Depth | | | |
| Drive Lugs | | | |
| Alignment | | | |
| Idler Condition | | | |



| | | | |
|------------------------|--|--|---|
| Tensioner Condition | | | |
| Overall Comments | | | Tractor is in excellent condition. Could not find a fault. No Fault Codes. Very well looked after. |



















2750
24-4-25

























JOHN DEERE

Default Tractor Run Page

12:33

SF1



JOHN DEERE



Diagnostics Center



Sort by:

Status



System Diagnostics

Type

Code

Status

Count

Controllers



Operator presence system.
XSC.001 | 1504.14 | Vehicle

Inactive

7

CAN Bus Info

Network

Ethernet Bus Info

Sharing



Refresh



Clear All Codes

X



ITEC

