

Date: 23/07/2025

Location: Moama, NSW

Machine Type: Pick Up Front

Make: 2011 Phillips

Model: Rollerdown Pick Up Front

Serial Number: TR10-004011

Clean: ☒ Yes/☐ No

Covers off: Yes/☒ No

Operated: Yes/No

Visual Inspection

Front is in very good condition.

No Leaks or cracks found.

No bad bearings found.


Drive chain and sprocket look ok

Drum and retractable fingers look ok.

Pick up belt and tines look ok.

Chain and Flat drive sprocket for bar real look a little worn

Front was not on header and not run.





22T/28M³

DUNSTAN







































