



Lot 3

Date: **05/08/2025**

Location: **Ouyen, Victoria**

Machine Type: **4WD Tractor**

Make: **Case IH**

Model: **2009 Steiger 485**

Hours: **7140**

Serial Number: **Z9F112970**

Auto Steer: **Pro 700 + 372 Receiver**

Clean: **Yes/No**

Transmission: **Powershift**

Engine Oil Analysis: **Yes/No**

Hydraulic Oil Analysis: **Yes/No**

Coolant Analysis: **Yes/No**

Diff/Planetary/Main Gearbox: **Yes/No**

**** NO PTO ****

Visual Inspection

Item	OK	Not Ok	Comments
Engine Oil	✓		
Engine Temperature	✓		
Last Service	✓		
Leaks	✓		
Filters	✓		
Air Cleaner	✓		
Turbo/Exhaust	✓		Exhaust gas leak detected. Possibly in flex piece
Wiring/Alternator	✓		
Belts/Hoses/Clamps	✓		
Radiator	✓		
Oil Coolers	✓		
Screen	✓		
Fuel Pump	✓		
Fuel Injectors	✓		
Fuel Tank	✓		
Batteries	✓		
Corrosion	✓		
Covers/Guards	✓		
Front Planetary Seals	✓		
Rear Axle Seals	✓		
Front Diff	✓		
Rear Diff	✓		
Drive Shafts	✓		
Suspension			
Recent Repairs	Rocker Cover Gasket		



Transmission & Hydraulics

Oil Level	✓		
Transmission	✓		
Powershift	✓		
IVT/CVT			N/A
Hyd Pumps	✓		
Hyd Cylinders	✓		
Valve Blocks	✓		
Steering	✓		
Remote Couplings	✓		
Leaks	✓		Breather on top of hyd oil tank – keep clean. Air in/out when steering
Three Point Linkage			Not fitted

Cab, Electrical and Tyres

Cab			
Air Conditioner	✓		
Radio	✓		
Two-way Radio	✓		
Windows	✓		
Upholstery	✓		
Seat Condition/Function	✓		Seat airbag does not pump up
Switches	✓		
Function Controls	✓		
Lights	✓		
Screens	✓		
Monitors	✓		
Mounting Points	✓		
Overall Condition And Comments			Very Good to Excellent condition. Seat airbag may need attention
Tyres			
Tyre Size	✓		Rear mounted weights. Front Axle weights 800/70/R38
Duals	✓		
Wheel Condition	✓		
Tyre Condition	✓		One small split. Right, front, outer
Tread Depth			Average 40mm
Tracks			
Track Condition			
Tread Depth			
Drive Lugs			
Alignment			
Idler Condition			



Tensioner Condition			
Overall Comments			Very Good to Excellent Condition

