



Tractors

Date: 15/07/2025	Locatic	n: Young	g NSW	Machine Type: FWA Tractor	
Make: Case IH	Location: Young NSW Model: Puma 140			<u>Hours</u> : 2680	
Serial Number: ZGBL53147				<u>Auto Steer</u> : No	
<u>Clean</u> : <mark>Yes</mark> /No				Transmission:	
Engine Oil Analysis:	Yes/ <mark>No</mark>			Hydraulic Oil Analysis:	Yes/ <mark>No</mark>
Coolant Analysis:	Yes/ <mark>No</mark>			Diff/Planetary/Main Gearbox:	Yes/ <mark>No</mark>
Burder 9050 FEL					
Visual Inspection					
Item	ОК	Not Ok		Comments	
Engine Oil					
Engine			Infrared Thern	nal Test:	
Temperature	(
Last Service	 		Service Due		
Leaks	V (
Filters	\checkmark				
Air Cleaner	\checkmark				
Turbo/Exhaust					
Wiring/Alternator	~				
Belts/Hoses/Clamps	~				
Radiator	~				
Oil Coolers	 ✓ 				
Screen	\checkmark				
Fuel Pump	~				
Fuel Injectors	~				
Fuel Tank	~				
Batteries	>				
Corrosion	~				
Covers/Guards	~				
Front Planetary Seals	 ✓ 	()	6		
Rear Axle Seals	\checkmark				
Front Diff	\checkmark				
Rear Diff	\checkmark				
Drive Shafts	\checkmark				
Suspension	~				
Recent Repairs		. <u></u>			





Transmission & Hydraulics

Oil Level	~	
Transmission	\checkmark	
Powershift	>	
IVT/CVT		N/A
Hyd Pumps	>	
Hyd Cylinders	>	
Valve Blocks	>	
Steering		
Remote Couplings	>	
Leaks	>	
Three Point Linkage	X	Top Link Bent

Cab, Electrical and Tyres

Cab		
Air Conditioner		
Radio	V (
Two-way Radio		
Windows		
Upholstery		
Seat Condition/Function		
Switches		
Function Controls		
Lights	✓	
Screens	✓	
Monitors	\checkmark	
Mounting Points	✓	
Overall Condition And Comments		Cab is in good condition. Slight mouse smell (Wurth make a cab deodoriser bomb that will remove this smell)
Tyres		6
Tyre Size		Rear 600/65/38 Front 480/65/28
Duals		
Wheel Condition	\checkmark	
Tyre Condition	\checkmark	
Tread Depth		50%
Tracks		
Track Condition		
Tread Depth		
Drive Lugs		
Alignment		
Idler Condition		





Tensioner Condition	
Overall Comments	Tractor is in good condition. Slightly untidy. Mouse smell in cab. Full Service Due.

