



Tractors

Date: 15/07/2025 Location: Young NSW

Machine Type: Tracked Tractor

Make: John Deere Model: 8RT 370

Hours: 2076hrs

Serial Number: 1RW8370DLMF925609

Auto Steer: John Deere

Clean: Yes/No

Transmission: Powershift

Engine Oil Analysis: Yes/No

Hydraulic Oil Analysis: Yes/No

Coolant Analysis: Yes/No

Diff/Planetary/Main Gearbox: Yes/No

Visual Inspection

Item	OK	Not Ok	Comments
Engine Oil	✓		
Engine Temperature	✓		
Last Service	✓		Service Due
Leaks	✓		
Filters	✓		
Air Cleaner	✓		
Turbo/Exhaust	✓		
Wiring/Alternator	✓		
Belts/Hoses/Clamps	✓		
Radiator	✓		
Oil Coolers	✓		
Screen	✓		
Fuel Pump	✓		
Fuel Injectors	✓		
Fuel Tank	✓		
Batteries	✓		
Corrosion	✓		
Covers/Guards	✓		
Front Planetary Seals			
Rear Axle Seals	✓		
Front Diff			
Rear Diff	✓		
Drive Shafts	✓		
Suspension	✓		
Recent Repairs			



Transmission & Hydraulics

Oil Level	✓		
Transmission	✓		
Powershift	✓		
IVT/CVT			
Hyd Pumps	✓		
Hyd Cylinders	✓		
Valve Blocks	✓		
Steering	✓		
Remote Couplings	✓		
Leaks	✓		
Three Point Linkage	✓		

Cab, Electrical and Tyres

Cab			
Air Conditioner	✓		
Radio	✓		
Two-way Radio	✓		
Windows	✓		
Upholstery	✓		
Seat Condition/Function	✓		
Switches	✓		
Function Controls	✓		
Lights	✓		
Screens	✓		
Monitors	✓		
Mounting Points	✓		
Overall Condition And Comments			Cab Is in Very Good Condition
Tyres			
Tyre Size			
Duals			
Wheel Condition			
Tyre Condition			
Tread Depth			
Tracks			
			25 Inch Tracks on 2100mm Centres
Track Condition	✓		50mm
Tread Depth	✓		
Drive Lugs	✓		Right Track Drive Lugs have slight damage and uneven wear
Alignment	✓		Right Track looks to be slightly out of alignment
Idler Condition	✓		



Tensioner Condition	✓		Front Tensioner Bushe look to be under greased
Overall Comments			<p>Right Side Track looks to be slightly out of alignment. Perform Track tension calibration, ensure front track tension bush takes and gets adequate grease. Perform Straight steering test and correct alignment over time.</p> <p>Otherwise, Tractor is in very good, to excellent condition</p>

