



## Tractors

Date: 18/03/2024      Location: AR Gatton      Machine Type: FWA Tractor 300HP+  
Make: Case IH      Model: Magnum 340      Hours: 6283 hrs  
Serial Number: ZDRZ07124      Auto Steer: Trimble  
Clean: Yes/No      As Traded      Transmission: 19 Speed Powershift  
Engine Oil Analysis: Yes/No      Hydraulic Oil Analysis: Yes/No  
Coolant Analysis: Yes/No      Diff/Planetary/Main Gearbox: Yes/No

## Visual Inspection

Item	OK	Not Ok	Comments
Engine Oil	✓		
Engine Temperature	✓		Infrared Thermal Test: All 6 cylinders good
Last Service	✓		6000hrs
Leaks	✓		No Visible leaks
Filters	✓		Changed 6000hrs
Air Cleaner	✓		Changed 6000hrs
Turbo/Exhaust	✓		
Wiring/Alternator	✓		Test – Multimeter: Good
Belts/Hoses/Clamps	✓		
Radiator	✓		Clean and straight
Oil Coolers	✓		Clean
Screen	✓		Clean
Fuel Pump	✓		
Fuel Injectors	✓		
Fuel Tank	✓		
Batteries	✓		
Corrosion	✓		
Covers/Guards	✓		
Front Planetary Seals	✓		
Rear Axle Seals	✓		
Front Diff	✓		
Rear Diff	✓		
Drive Shafts	✓		
Suspension	✓		Slight weep in suspension rams
<b>Recent Repairs</b>	Some electrical repairs under cab on right side		



### Transmission & Hydraulics

Oil Level	✓		
Transmission	✓		18 Forward 6 Reverse
Powershift	✓		
IVT/CVT			N/A
Hyd Pumps	✓		
Hyd Cylinders	✓		
Valve Blocks	✓		
Steering	✓		
Remote Couplings	✓		
Leaks	✓		
Three Point Linkage	✓		

### Cab, Electrical and Tyres

<b>Cab</b>			
Air Conditioner	✓		
Radio	✓		
Two-way Radio		X	No two way
Windows	✓		
Upholstery		X	Used. Leather on seat is Cracked
Seat Condition/Function	✓		All Functions work
Switches	✓		
Function Controls	✓		Linkage/Remote levers: All functions work
Lights	✓		
Screens	✓		
Monitors	✓		
Mounting Points	✓		
Overall Condition And Comments			Good condition. As Traded. Seat leather cracked
<b>Tyres</b>			
Tyre Size	✓		Rear 480/80/50 Front 480/70/34
Duals	✓		As New. Front and Rear Duals
Wheel Condition	✓		
Tyre Condition	✓		
Tread Depth	✓		
<b>Tracks</b>			N/A
Track Condition			
Tread Depth			
Drive Lugs			
Alignment			



Idler Condition			
Tensioner Condition			
Overall Comments			<p>Tractor is in good working condition. Relatively low hours. Slight weep in Suspension rams, wiper seal is working. Repairs or electrical/hydraulic valve block visible under cab on the right hand side.</p> <p>Hydraulic oil/filter may need service – see oil analysis</p>