



## **Tractors**

<u>Date:</u> 29/03/2025	Location: Biloela, Qld	Machine Type: 4WD Tractor	
Make: Case IH	Model: STX375	<u>Hours</u> : 6145	
Serial Number: JEE010	5309	<u>Auto Steer</u> : No	
<u>Clean</u> : Yes/No		Transmission: 24/6 Syncromesh	I
Engine Oil Analysis:	<mark>Yes</mark> /No	Hydraulic Oil Analysis:	Yes/ <mark>No</mark>
Coolant Analysis:	Yes/ <mark>No</mark>	Diff/Planetary/ <mark>Main Gearbox</mark> :	<mark>Yes</mark> /No

## Visual Inspection

Item	ОК	Not Ok	Comments
Engine Oil		X	Separated Engine Oil
Engine	NY.		Infrared Thermal Test:
Temperature			
Last Service		X	Major Service Required
Leaks	~		
Filters	<ul> <li></li> </ul>		
Air Cleaner	~		
Turbo/Exhaust			
Wiring/Alternator	~		
Belts/Hoses/Clamps	~		
Radiator	~		
Oil Coolers	~		
Screen	~		
Fuel Pump			
Fuel Injectors			
Fuel Tank	~		
Batteries	~		
Corrosion	~		
Covers/Guards	~		
Front Axle Seals	<ul> <li>Image: A second s</li></ul>		
Rear Axle Seals	~		Right Axle Seal Leak
Front Diff	<ul> <li></li> </ul>		Slight Gasket Leak
Rear Diff	~		
Drive Shafts	<ul> <li></li> </ul>		Needs Grease
Suspension			N/A
Recent Repairs			





## Transmission & Hydraulics

Oil Level			
Transmission	<		Synchro Trans has had repairs + Clutch Sensor
Powershift			
IVT/CVT			N/A
Hyd Pumps	<		
Hyd Cylinders	<		
Valve Blocks	<		
Steering	~		Pivot Points Need More Grease
Remote Couplings	<		
Leaks	~		
Three Point Linkage		1	

## Cab, Electrical and Tyres

Cab		
Air Conditioner		
Radio		
Two-way Radio		
Windows		
Upholstery		
Seat Condition/Function		
Switches		
Function Controls		
Lights		
Screens		
Monitors		
Mounting Points		
Overall Condition And Comments	Armrest has been apart. LCD Screens are fadir	15
Tyres		
Tyre Size	620/70/42	
Duals	$\checkmark$	
Wheel Condition	$\checkmark$	
Tyre Condition	✓ One Front Tyre Flat	
Tread Depth	50%	
Tracks		
Track Condition		
Tread Depth		
Drive Lugs		
Alignment		
Idler Condition		





Tensioner Condition		
Overall Comments	See Engine Oil Ana	arated. On checking pre start. Iysis. hery Mate for Comments

