

 Date:
 20/06/2024
 Location:
 Black Truck & Ag Gatton

Machine Type: Feed Mixer

Make: Strautmann

Model: Verti – Mix 2401 Double

Serial Number: WC9658105LOS38192 - 2020

<u>Clean</u>: Yes/No

<u>Operated</u>: Yes/<mark>No</mark>

<u>Covers off</u>: <mark>Yes</mark>/No

## Visual Inspection

ltem	ОК	Not OK	Comments
Pull & Frame	~		
			5
PTO Shafts	$\checkmark$		Waltersheid
		$\cap$	
Hyd Hoses & Rams	~		
Hyd Motors	V		
Mixer Rotors	$\checkmark$	Y	Look to be in good condition
Rotor Gearboxes	$\checkmark$		No Visible leaks Recommend that oil samples be taken
			Recommend that of samples be taken
			* <mark>Missing Elevator belt</mark> * <mark>Missing Scales</mark>
Overall			Appears to be in very good condition Request that it be hooked onto a tractor, ran and oil samples taken from gearboxes.
		<b>(</b> ,	
		C/	
<u> </u>			