

<u>Date:</u> 18/06/2024 Location: AR Gatton

Machine Type: Mower/Conditioner

Make: Taarup Model: 4232 LR

Serial Number: 403893

<u>Clean</u>: Yes/No <u>Covers off</u>: Yes/No

Operated: Yes/No

Visual Inspection

Item	ОК	Not OK	Comments
Pull & Frame		OK.	No Visible Cracks
		1	
PTO Shafts	V		Walterscheid
Hydraulic lines &			Hyd hose off cutterbar lift
Hoses	1		No other visible faults
Cutterbar	V		Needs new blades
Conditioning			Pollors are stuffed. Pubber is disintegrating
Rollers	X	10	Rollers are stuffed. Rubber is disintegrating. New Rollers are needed
Tionors			Foil Crimp test in photos
Overall			Machine needs new conditioning rollers
		\wedge	
		1	
			3



