



## Tractors

Date: 14/06/2024    Location: 524 Quinalow – Peranga Rd, Peranga

Machine Type: Small Tractor. FWA

Make: Ursus

Model: 5314

Hours: 0928hrs

Serial Number: 4028262C91 1562/10/95

Auto Steer: No

Clean: Yes/No

Transmission: 6F 2R with creeper gears

Engine Oil Analysis: Yes/No

Hydraulic Oil Analysis: Yes/No

Coolant Analysis: Yes/No

Diff/Planetary/Main Gearbox: Yes/No

Operated: Yes/No

Start and Run: Yes/No

### Visual Inspection

Item	OK	Not Ok	Comments
Engine Oil	✓		Feels thin. Smells slightly Diesely
Engine Temperature			Infrared Thermal Test: NO
Last Service		X	Unknown
Leaks	✓		Slight diesel leak around injector lines
Filters	✓		
Air Cleaner	✓		
Turbo/Exhaust	✓		No Turbo
Wiring/Alternator	✓		
Belts/Hoses/Clamps	✓		
Radiator	✓		
Oil Coolers	✓		
Screen	✓		
Fuel Pump	✓		New Lift pump
Fuel Injectors	✓		Slight leak around injector lines coming out of fuel pump
Fuel Tank	✓		
Batteries	✓		
Corrosion	✓		
Covers/Guards	✓		No PTO Guard
Front Planetary Seals	✓		
Rear Axle Seals	✓		Slight weep in right rear axle seal
Front Diff	✓		
Rear Diff	✓		
Drive Shafts	✓		
Suspension	✓		
Recent Repairs	New Lift Pump		



### Transmission & Hydraulics

Oil Level	✓		
Transmission	✓		
Powershift	✓		
IVT/CVT			N/A
Hyd Pumps	✓		
Hyd Cylinders	✓		
Valve Blocks	✓		
Steering	✓		
Remote Couplings	✓		
Leaks	✓		Slight leak in rear right axle seal
Three Point Linkage	✓		
PTO		X	PTO not disengaging

### Cab, Electrical and Tyres

<b>Cab</b>			
Air Conditioner	✓		
Radio	✓		
Two-way Radio			Not Fitted
Windows	✓		
Upholstery	✓		
Seat Condition/Function	✓		
Switches	✓		
Function Controls	✓		
Lights	✓		
Screens			Analog Gauges. Tacho needle broken
Monitors			None fitted
Mounting Points			
Overall Condition And Comments			Cab is in good condition
<b>Tyres</b>			
Tyre Size			Front 12.4/24 Rear: 16.9/34
Duals			N/A
Wheel Condition	✓		
Tyre Condition	✓		
Tread Depth			Front: 18mm Rear: 30mm
<b>Tracks</b>			
Track Condition			
Tread Depth			
Drive Lugs			



Alignment			
Idler Condition			
Tensioner Condition			
Overall Comments	✓		<p>PTO Live while at idle.</p> <p>Otherwise tractor is in pretty good condition</p>

